

EY

**RECEIVED
CENTRAL FAX CENTER
MAY 31 2007**

Certificate
JUN 04 2007
of Correction

In the United States Patent and Trademark Office

Application No.: 10/043,423	§ Filing date: January 10, 2002
Patent No.: US 7,150,680 B2	§ Issue date: December 19, 2006
Title: DRIVE SHAFT COUPLING	§ Examiner: BINDA, Gregory John § Art Unit: 3679
Applicant: WHITTE, Patrick Michel	§ Docket No: PUS-P001-025

REQUEST FOR CERTIFICATE OF CORRECTION

FAX: 001 571 273 8300
 United States Patent and Trademark Office
 Attn.: Certificate of Corrections Branch,
 Commissioner for Patents
 P.O. Box 1450
 Alexandria, VA 22312-1450
 USA

Dear Sirs,

The undersigned attorney for applicant has noticed several errors in the above-identified Letters Patent.

Attached is a Certificate of Correction, which applicant asks be entered into the record and provided together with the issued patent document whenever anyone requests the same.

The undersigned authorizes the Commissioner to charge the deposit account of Moetteli & Associates SARL No. 50-2621 for any fee due. If the Commissioner has any questions, he is invited to contact the undersigned.

Respectfully,

John Moetteli
 US Patent Attorney-at-law
 Reg. No. 35,289

Date: 30 May 2007

Encl.: as mentioned

PTO/SB/44 (04-05)

Approved for use through 04/30/2007. OMB 0651-0033

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,150,680 B2

Page 1 of 1

APPLICATION NO.: 10/043,423

ISSUE DATE : December 19, 2006

INVENTOR(S) : WHITE, Patrick Michel

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In Col. 7, line 66, replace the phrase "This smoother transition ensures premature failure of fitting 20." with --This smoother transition ensures against premature failure of fitting 20.--.

In Col. 8, line 38, delete the "," at the end of the line.

In Col. 8, line 49, replace the phrase "surface to surface" with --surface-to-surface--.

In Col. 10, line 2, replace the phrase "with the an aperture" with --with the aperture--.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

MOETTELI & Asssociés SaRL
 St. Leonhardstrasse 4
 CH-9000 St. Gallen, Switzerland

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.